

**STRAIGHT LINE DIAGRAM
N^o 10
DIRECT CURRENT WIRING.**



